



Safety Data Sheet

70% ISOPROPYL RUBBING ALCOHOL

Section 1. Identification

Product Identifier	70% ISOPROPYL RUBBING ALCOHOL		
Synonyms	MDS098003Z; MDS098010; MDS098011; MDS098012; MDS098013; MDS098016; MDS098017; MSD_SDS0048		
Manufacturer Stock Numbers	MDS098003Z; MDS098010; MDS098011; MDS098012; MDS098013; MDS098016; MDS098017		
Recommended use	N/A		
Uses advised against	N/A		
Manufacturer Contact Address	Medline Industries, Inc. 3 Lakes Drive Northfield, IL, 60093 USA		
Phone	Emergency Phone	Fax	
(800) 633-5463	(800) 424-9300 CHEMTREC	(847) 643-4436	
Website	www.Medline.com		

Section 2. Hazards Identification

Classification	ACUTE TOXICITY - DERMAL - Category 5 ACUTE TOXICITY - ORAL - Category 5 EYE DAMAGE/IRRITATION - Category 2B FLAMMABLE LIQUIDS - Category 3 SENSITIZATION - SKIN - Category 1B
Signal Word	Warning
Pictogram	Two red diamond-shaped pictograms. The first contains a black flame icon, representing a flammable liquid. The second contains a black exclamation mark icon, representing a general health hazard.
Hazard Statements	Causes eye irritation

Flammable liquid and vapor
May be harmful if swallowed
May be harmful in contact with skin
May cause an allergic skin reaction

Precautionary Statements

Response

Call a poison center/doctor if you feel unwell.
If eye irritation persists: Get medical advice/attention.
If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower.
If on skin: Wash with plenty of water.
If skin irritation or rash occurs: Get medical advice/attention.
In case of fire: Use appropriate media to extinguish.
Wash contaminated clothing before reuse.

Prevention

Avoid breathing dust/fume/gas/mist/ vapors/spray.
Contaminated work clothing must not be allowed out of the workplace.
Ground/bond container and receiving equipment.
Keep away from heat.
Keep container tightly closed.
Take precautionary measures against static discharge.
Use explosion-proof electrical/ventilating/lighting equipment.
Use only non-sparking tools.
Wash affected area thoroughly after handling.
Wear protective gloves.
Wear protective gloves/eye protection/face protection

Storage

Store in a well-ventilated place. Keep cool.

Disposal

Dispose of contents/container in accordance with federal, state and local environmental control regulations.

Ingredients of unknown toxicity

N.A.

Hazards not Otherwise Classified

No Data Available

Section 3. Ingredients

CAS	Ingredient Name	Weight %
67-63-0	Isopropyl alcohol	70 %

Occupational exposure limits, if available, are listed in Section 8.

Section 4. First-Aid Measures

General Advice:	Take proper precautions to ensure your own health and safety before attempting rescue and providing first aid. Consult a physician. Show this safety data sheet to the doctor in attendance. Move out of dangerous area.
Eye Contact:	Flush eyes with large amounts of water for at least 15 minutes. Remove contact lenses, if worn. If irritation persists, seek medical attention.
Skin Contact:	Wash with soap and water; if irritation persists, seek medical attention.
Inhalation:	Remove victim to fresh air. Seek medical attention if discomfort continues.
Ingestion:	If swallowed, call a physician immediately. Rinse mouth and throat thoroughly with water. Do not induce vomiting unless directed to do so by a physician. Never give anything by mouth to an unconscious person. If vomiting occurs spontaneously, keep head below hips to prevent aspiration of liquid into lungs.

Section 5. Fire Fighting Measures

Suitable Extinguishing Media	In case of fire, use Water spray, Carbon Dioxide (CO ₂), Foam, Dry Chemical
Unsuitable Extinguishing Media	N.D.
Unusual Fire and Explosion Hazards:	N.D.
Special Fire Fighting Procedures:	N.D.

Section 6. Accidental Release Measures

Flammable Small Spill:	Absorb with an inert dry material and place in an appropriate waste disposal container.
Flammable Large Spill:	Flammable liquid. Keep away from heat. Keep away from sources of ignition. Stop leak if without risk. Absorb with dry earth, sand or other non-combustible material. Do not touch spilled material. Prevent entry into sewers, basements or confined areas; dike if needed.

Section 7. Handling and Storage

Handling Flammable:	Keep away from heat. Keep away from sources of ignition. Ground all equipment containing material. Do not ingest. Do not breathe gas/ fumes/ vapor/ spray. Avoid contact with eyes. Wear suitable protective clothing. In case of insufficient ventilation, wear suitable respiratory equipment. If ingested, seek medical advice immediately and show the container or the label. Keep away from incompatibles such as oxidizing agents, acids.
Storage Flammable:	Store in a segregated and approved area. Keep container in a cool, well-ventilated area. Keep container tightly closed and sealed until ready for use. Avoid all possible sources of ignition (spark or flame).

Section 8. Exposure Controls/Personal Protection

Occupational Exposure Limits	Ingredient Name	ACGIH TLV	OSHA PEL	STEL
	Isopropyl alcohol	TWA: 200 ppm STEL: 400 ppm	TWA: 400 ppm STEL: 500 ppm	N/A
Personal Protective Equipment	Goggles, Gloves			
Engineering Controls:	Ventilation: Local exhaust.			
Respiratory Protection:	Air supplied masks or respirator in confined areas			
Skin Protection:	Protective gloves: Rubber Protective gloves: Vinyl.			
Eye Protection:	Wear chemical safety goggles while handling this product. Do not wear contact lenses. Wear additional eye protection such as face shield when the possibility exists for eye contact with splashing or spraying liquid, or airborne material.			
Other protective equipment:	Not expected to be necessary under normal conditions of use. Where exposure cannot be adequately controlled, use appropriate protective clothing or equipment			
Work/hygienic practices:	Handle in accordance with good industrial hygiene and safety practice. Wash thoroughly with soap and water after handling and before eating, drinking, or using tobacco. Safety shower and eye wash should be available close to work areas.			

Section 9. Physical and Chemical Properties

Physical State	Liquid
Color	Colorless
Odor	Characteristic odor
Odor Threshold	N.D.
Solubility	Complete
Partition coefficient Water/n-octanol	N.D
VOC%	N/A
Viscosity	N.D.
Specific Gravity	0.88
Density lbs/Gal	N/A
Pounds per Cubic Foot	N/A
Flash Point	22°C/72°F
FP Method	TCC
Ph	N.D.
Melting Point	N.A.
Boiling Point	87° C
Boiling Range	N.D.
LEL	2
UEL	12
Evaporation Rate	2.3
Flammability	N.D.
Decomposition Temperature	N.D.
Auto-ignition Temperature	N.D.
Vapor Pressure	33mmHg
Vapor Density	2.07

Section 10. Stability and Reactivity

Stability:	Stable.
Reactivity:	None
Incompatibility (Materials to avoid):	N.D.
Hazardous Decomposition or Byproducts:	Burning may produce Carbon Monoxide, Carbon Dioxide and other hazardous components.
Hazardous Polymerization	N.D.
Conditions to avoid:	Keep away from heat. Sparks. Open flame.

Section 11. Toxicological Information

Acute Toxicity: Eye Contact	Contact may cause temporary moderate irritation
Acute Toxicity: Skin Contact	May cause mild irritation on patients with sensitive skin
Acute Toxicity: Inhalation	N.A.
Acute Toxicity: Ingestion	May be harmful if swallowed
Carcinogenicity:	None known
Chronic Toxicity:	None known

Section 12. Ecological Information

Toxicity:	N.D.
Persistence and degradability:	N.D.
Bioaccumulative potential:	N.D.
Mobility in soil:	N.D.
Other adverse effects:	N.D.

Section 13. Disposal

Waste Disposal:	Waste must be disposed of in accordance with federal, state and local environmental control regulations.
-----------------	--

Section 14. Transport Information

UN Number	1219
UN Proper Shipping Name	Isopropanol, 3
DOT Classification	Hazmat at all levels depending on size of packaging, Excepted or Limited Quantity or Fully Regulated
Packing Group	PG II
Additional Information	IATA OR IMDG - UN1219, Isopropanol,3, PG II

Section 15. Regulatory Information

SARA 311/312:	N.A.
SARA 302:	N.A.
SARA 313:	Isopropyl alcohol.
TSCA:	N.A.
CERCLA Hazardous Substance List:	N.A.
Clean Air Act (CAA) Section 112, 112 (r):	N.A.
New Jersey Right to Know Components:	Isopropyl Alcohol
Pennsylvania Right to Know Components:	2-PROPANOL.
Rhode Island Right to Know Components:	isopropyl alcohol.

Section 16. Other Information

Revision Date 05/04/2017

Legend N.A. - Not Applicable
N.E. - Not Established
N.D. - Not Determined

HMIS (U.S.A.): Health Hazard 1

HMIS (U.S.A.): Flammability 3

HMIS (U.S.A.): Reactivity 1

National Fire Protection
Association (U.S.A): Health
Hazard 1

National Fire Protection
Association (U.S.A):
Flammability 3

National Fire Protection
Association (U.S.A):
Reactivity 1

Additional Information The information contained herein is furnished without warranty or legal responsibility of any kind. Employers should use this information only as a supplement to other information gathered by them and must make independent determination of suitability and completeness of information from all sources to assure proper use of these materials and the safety and health of employees